



DSCN0184.jpg Date: 6/10/13 Time: 12:55 Direction: West
Vacuum Tower in Crude Unit (fire occurred in this area).




DSCN0185.jpg Date: 6/10/13 Time: 12:59 Direction: North
Crude Unit.



DSCN0186.jpg Date: 6/10/13 Time: 13:01 Direction: Inside
Data display terminals in Crude Unit shelter.



DSCN0187.jpg Date: 6/10/13 Time: 13:03 Direction: Northwest
Crude Unit distillation towers.



DSCN0188.jpg Date: 6/10/13 Time: 13:06 Direction: North
Crude Unit product lines.



DSCN0189.jpg Date: 6/10/13 Time: 13:07 Direction: Northwest/Up
Labeled pipe in Crude Unit area.



DSCN0190.jpg Date: 6/10/13 Time: 13:09 Direction: Northeast
Crude heater.



DSCN0191.jpg Date: 6/10/13 Time: 13:10 Direction: East
Crude Unit heat exchangers.




DSCN0192.jpg Date: 6/10/13 Time: 13:12 Direction: North/Up
North and South Crude Unit vacuum heater.




DSCN0193.jpg Date: 6/10/13 Time: 13:13 Direction: North/Up
South vacuum heater stack.



DSCN0194.jpg Date: 6/10/13 Time: 13:19 Direction: West
Horizontal pipes in Crude Unit where fire occurred.



DSCN0195.jpg Date: 6/10/13 Time: 13:26 Direction: Inside/Southeast
Main control room – Crude Unit area.



DSCN0196.jpg Date: 6/10/13 Time: 13:27 Direction: Southwest
Main control room – Sulfur/Coker area.



DSCN0197.jpg Date: 6/10/13 Time: 13:32 Direction: Southwest
Naphtha Unit/Reformer #1.



DSCN0198.jpg Date: 6/10/13 Time: 13:38 Direction: East
Reactor in Reformer Unit.



DSCN0199.jpg Date: 6/10/13 Time: 13:41 Direction: East-Northeast
Reformer Unit heat exchangers.



DSCN0200.jpg Date: 6/10/13 Time: 13:47 Direction: West
Hydro cracker (partial).



DSCN0201.jpg Date: 6/10/13 Time: 13:49 Direction: West-Northwest
Hydrocracker heat exchangers.



DSCN0202.jpg Date: 6/10/13 Time: 13:56 Direction: West
Hydrocracker fractionation.



DSCN0203.jpg Date: 6/10/13 Time: 14:06 Direction: South
Clean Diesel Unit.



DSCN0204.jpg Date: 6/10/13 Time: 14:09 Direction: East
#3 Diesel Unit.



DSCN0205.jpg Date: 6/10/13 Time: 14:10 Direction: West
#2 Diesel Unit.



DSCN0206.jpg Date: 6/10/13 Time: 14:13 Direction: Northeast
#3 Diesel Unit.



DSCN0207.jpg Date: 6/10/13 Time: 14:15 Direction: Northeast
#3 Diesel reactor.

Facility: BP Cherry Point Refinery
Location: Blaine, Washington

EPA ID No.: 1000 0004 8307



DSCN0208.jpg Date: 6/10/13 Time: 14:15 Direction: Northeast
#3 Diesel high pressure heat exchangers.



DSCN0209.jpg Date: 6/10/13 Time: 14:17 Direction: Southwest
#3 Diesel Unit.



DSCN0210.jpg Date: 6/11/13 Time: 14:01 Direction: Southeast
#3 Diesel heat exchangers.




DSCN0211.jpg Date: 6/11/13 Time: 14:02 Direction: South
#3 Diesel heat exchangers.



DSCN0212.jpg Date: 6/11/13 Time: 14:14 Direction: West
#3 Diesel HPS level control valve 194A.



DSCN0213.jpg Date: 6/11/13 Time: 14:15 Direction: Southwest
#3 Diesel HPS level control valve 194B.



DSCN0214.jpg Date: 6/11/13 Time: 14:17 Direction: West
194B name plate.



DSCN0215.jpg Date: 6/11/13 Time: 14:20 Direction: East
Locked-out heat trace switch in #3 Diesel.




DSCN0216.jpg Date: 6/11/13 Time: 14:23 Direction: South
Pipe rack between #2 and #3 DHDS.



DSCN0217.jpg Date: 6/11/13 Time: 14:27 Direction: West
Pipe rack across from Hydrogen Plant.



DSCN0218.jpg Date: 6/12/13 Time: 09:47 Direction: Inside
North Fire Hall trailer-mounted foam monitor



DSCN0219.jpg Date: 6/12/13 Time: 09:47 Direction: Inside
North Fire Hall inspection board.



DSCN0220.jpg Date: 6/12/13 Time: 09:50 Direction: Inside
Foam tanker truck.



DSCN0221.jpg Date: 6/12/13 Time: 09:51 Direction: Inside
North Fire Hall SCBA.



DSCN0222.jpg Date: 6/12/13 Time: 09:52 Direction: Inside
North Fire Hall turn out gear.



DSCN0223.jpg Date: 6/12/13 Time: 09:53 Direction: Inside
North Fire Hall fire pump, pumper truck, and foam totes.



DSCN0224.jpg Date: 6/12/13 Time: 09:53 Direction: Inside
North Fire Hall.



DSCN0225.jpg Date: 6/12/13 Time: 09:58 Direction: West
South Fire Hall.




DSCN0226.jpg Date: 6/12/13 Time: 10:04 Direction: South
Semi-truck for foam trailer.



DSCN0227.jpg Date: 6/12/13 Time: 10:05 Direction: West
Ambulance in South Fire Hall.



DSCN0228.jpg Date: 6/12/13 Time: 10:06 Direction: Inside
Pump trailer, 100' ladder truck, and fire truck.



DSCN0229.jpg Date: 6/12/13 Time: 10:07 Direction: Inside
South Fire Hall turn out gear.



DSCN0230.jpg Date: 6/12/13 Time: 10:08 Direction: Inside
8,000 gallon per minute monitor.



DSCN0231.jpg Date: 6/12/13 Time: 10:14 Direction: Inside
Shift fire team schedule.



DSCN0232.jpg Date: 6/12/13 Time: 10:17 Direction: Inside
Mobile command post.



DSCN0233.jpg Date: 6/12/13 Time: 10:19 Direction: Southeast
SCBA on east side of Diesel unit (at Stanchion #37-4).



DSCN0234.jpg Date: 6/12/13 Time: 10:23 Direction: Northeast
I & E Building.



DSCN0235.jpg Date: 6/12/13 Time: 13:37 Direction: Northwest
MSC tool room and shop.



DSCN0236.jpg Date: 6/12/13 Time: 13:38 Direction: North
I & E Shop.




DSCN0237.jpg Date: 6/12/13 Time: 13:40 Direction: Northwest
Entrance to I & E Shop.



DSCN0238.jpg Date: 6/13/13 Time: 13:10 Direction: South
Crude Unit (beyond pipe rack).



DSCN0239.jpg Date: 6/13/13 Time: 13:20 Direction: Up
Vacuum tower bottoms outlet piping.



DSCN0240.jpg Date: 6/13/13 Time: 13:24 Direction: Up
Vacuum tower.



DSCN0241.jpg Date: 6/13/13 Time: 13:25 Direction: Up/South
Ultrasonic flow meter.



DSCN0242.jpg Date: 6/13/13 Time: 13:26 Direction: East
Valve and gauge (beyond maximum gauge range) LV-10-100.



DSCN0243.jpg Date: 6/13/13 Time: 13:29 Direction: East
Valve and gauge (beyond maximum gauge range) LV-10-100.



DSCN0244.jpg Date: 6/13/13 Time: 13:31 Direction: East/Up
Gauge on vacuum bottoms piping.



DSCN0245.jpg Date: 6/13/13 Time: 13:35 Direction: West/Up
Vacuum start-up line.



DSCN0246.jpg Date: 6/13/13 Time: 13:36 Direction: South/Up
Vacuum start-up line/stagnant line where thermal syphon and fire occurred.



DSCN0247.jpg Date: 6/13/13 Time: 13:51 Direction: South
Reformer Naphtha Unit.



DSCN0248.jpg Date: 6/13/13 Time: 13:57 Direction: East
NHDS reactor.



DSCN0249.jpg Date: 6/13/13 Time: 14:21 Direction: West
Hydro cracker.



DSCN0250.jpg Date: 6/13/13 Time: 14:35 Direction: West
Hydrocracker heat exchangers.



DSCN0251.jpg Date: 6/13/13 Time: 14:38 Direction: North
Temperature gauge.



DSCN0252.jpg Date: 6/13/13 Time: 14:39 Direction: North
Thermal well on heat exchanger piping.
